



Web-based Log Books for Aircraft &amp; Pilots!

305

[PlaneLog](#) | [Contact](#) | [Logout](#) | [Admin Page](#)

## N123PG -- Log Entry Details

Aircraft: N123PG  
Serial: 001450  
Date: December 5, 2000  
Tach: 1401.00  
Total Time: 1401.00

### Administrative Data

Date Entered: December 5, 2000  
Entering User: Client10 -- Client 10

705

This entry has been modified 3 times

The last modification was done for this reason:  
*Add Part Number*

[Modify Entry](#)

709

### Entry:

Removed nosefork, serviced & install new washers.PN 1234. Adjust fork tension.  
Install new o ring in primer, remove fuel selector, install new o-rings & lube  
reinstall. Ops check above ok A. Body A&P 123456789

506A



305

[PlaneLog](#) | [Contact](#) | [Logout](#) | [aircraft page](#)

## N123PG -- Log Entry Details

Aircraft: N123PG  
Serial: 001450  
Date: December 4, 2000  
Tach: 1200.00  
Total Time: 1200.00

### Administrative Data

Date Entered: December 4, 2000  
Entering User: Client10 -- Client 10

706


This is an original entry

[Modify Entry](#) 709

Entry Auth: Client 10  
Auth Cert #: 123546789  
Auth Cert: Private Pilot

506A  
Entry:

C/W AD 78-23-01 by inspection and operation of fuel drain level door. Reoccurring inspection is due each 100 hrs. C/W AD 9526-13 by inspection of oil cooler hoses in accordance with AMOC #1, Hoses are airworthy at this time. C/W AD 90-02-23L by inspection of Prop hub for cracks. Reoccurring inspection due every 50 hours or every 50 flights, which ever comes first. Dressed and painted prop. C/W AD 76 07-12 by ops check of bendix mag switch. Reoccurring inspection is due each 100 hrs. Installed hardware on throttle control cable end at throttle and on fuel servo as illustrated in AD 80-14-02 and SB 537. Replaced bottom left engine vibration dampener. Resealed right and left main gear strut, serviced with fresh Hyd oil & nitrogen. Serviced nose strut with fluid & nitrogen. Resealed left brake wheel cylinder. Lubed landing gear. Cleaned and replaced all wheel bearings. Serviced tires with air pressure. Replaced wheel fairings studs and retainers as needed. Replaced left inboard sump valve. Zip tied loose wires for stall warning. Replaced vac regulator filter adjusted tension of control yoke cross over chain. Lubed all pulleys, hinges, rod ends, serviced fuel strainer. Installed missing strainer filte spring. Inspected ELT in accordance with FAR 91.207(d) Elt Battery is due June 1988. Washed lead from bottom of A/C. Serviced Battery & brake res. Ground run- ops normal. I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.  
A. Body 123456789 A/P



Web-based Log Books for Aircraft & Pilots!

[Home](#) [Log Books](#) [Contact](#) [Logout](#)

305

N123PG - Log Entry Modification

Original Entry — 901

Date	Date Entered in System	Tach	Total Time	Entry
December 5, 2000		1400.00	1400.00	Removed nosefork, serviced & install new washers. Adjust fork tension. Install new o ring in primer, remove fuel selector, install new o-rings & tube reinstall. Ops check above ok A. Body A&P 123456789

Log Entry History — 902

Date	Date Entered in System	Tach	Total Time	Entry	Reason for Change
December 5, 2000		1400.00	1400.00	Removed nosefork, serviced & install new washers. Adjust fork tension. Install new o ring in primer, remove fuel selector, install new o-rings & tube reinstall. Ops check above ok A. Body A&P 123456789	Correct Total Time
December 5, 2000		1401.00	1401.00	Removed nosefork, serviced & install new washers. Adjust fork tension. Install new o ring in primer, remove fuel selector, install new o-rings & tube reinstall. Ops check above ok A. Body A&P 123456789	Correct Total Time
December 5, 2000		1401.00	1401.00	Removed nosefork, serviced & install new washers. PN 1234. Adjust fork tension. Install new o ring in primer, remove fuel selector, install new o-rings & tube reinstall. Ops check above ok A. Body A&P 123456789	Add Part Number

Modify Entry — 903

Reason for Change:

Authorizing User: <input type="text"/> Client 10 <input type="checkbox"/> Other	Name: <input type="text"/> A. Body	Unknown	Priv: <input type="text"/> unknown Repairs Cart A & P IA Private
---	------------------------------------	---------	--

Repair Station:   
Work Order:

Date Listed IS NOT Actual Log Entry Date  
(see date shown below) December 5, 2000

Month

Day:

Year

Entry:

Removed nosefork, serviced & install new washers. PN 1234. Adjust fork tension. Install new o ring in primer, remove fuel selector, install new o-rings & tube reinstall. Ops check above ok A. Body A&P 123456789
--

Tach:  1401.00 No Tach Entry.

Override Original Tachometer Adjustment (use TTAF shown below) Yes No

TTAF:

Events

General Events  
- none -  
Flight Test  
Annual Inspection  
Minor Repair  
New Parts  
Xbody / Mode C Reset  
Weight & Balance  
ETL Service

Major Events (Form 337)  
- none -  
SRC Modification  
Major Alteration (non-std)  
Major Repair

Modify previously entered Weight & Balance Data

406

Figure 8